

PETROLEUM RESIN 1104

APPLICATIONS

Adhesives

Construction Adhesives

Pressure Sensitive Adhesives

Inks

Sealants

TYPICAL PROPERTIES

Softening point, °C ring & ball : 90-100 °C

Color, Gardner ^a : 15

Glass Transition Temperature (T_g) : 34°C

Cloud point, MMAP : 26°C

Melt Viscosity ^b

10 poise : 160°C

100 poise : 135°C

1000 poise : 120°C

Molecular Weight ^c

M_n : 670

M_w : 1700

M_w/M_n : 2.5

M_z : 5500